State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



go

Michael O. Leavitt Governor

Ted Stewart
Executive Director
James W. Carter
Division Director

1394 West North Temple, Suite 12	210	
P.O. Box 145801	Partial: Complete: XXX Expl	oration.
Salt Lake City, Utah 84114-5801		
(801) 538-5340 Ins	pection Date & Time: 11/12/96 / 8:30a.m.	-
(801) 359-3940 (Fax)	Date of Last Inspection:	10/17/90

Mine Name: <u>Crandall Canyon Mine</u> County: <u>Emery</u> Permit Number: <u>ACT/015/032</u>								
Permittee and/or Operator's Name: Genwal Resources, Inc.								
Business Address: P.O. Box 1210, Huntington, Utah 84528								
Type of Mining Activity: Underground XXX Surface Prep. Plant Other								
Company Official(s): Gary Gray								
State Officials(s): Stephen J. Demczak Federal Official(s): None								
Weather Conditions: Cool, 30's								
Existing Acreage: Permitted-2165.42 Disturbed-5.55 Regraded-5 Seeded-5 Bonded-5.55								
Increased/Decreased: Permitted Disturbed Regraded Bonded								
Status: _Exploration/_XXX_Active/Inactive/Temporary Cessation/Bond Forfeiture								
Reclamation (_Phase I/_Phase II/_Final Bond Release/_LiabilityYear)								

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instruction

1. Substantiate the elements on this inspection by checking the appropriate performance standard.

a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.

b. For partial inspections check only the elements evaluated.

- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		E	VALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE		[XX]	ĪĪ	[XX]	
2.	SIGNS AND MARKERS		[XX]	ĹΪ	П	Ш
3.	TOPSOIL		<u>[XX]</u>	Ĺĺ	ĹĬ	\Box
4.	HYDROLOGIC BALANCE:					
a.	DIVERSIONS		[XX]	\Box	[XX]	
b.	SEDIMENT PONDS AND IMPOUNDMENTS		[XX]	Π	[XX]	LI.
c.	OTHER SEDIMENT CONTROL MEASURES		[XX]	$\overline{\Box}$	[XX]	ĹĹ
d.	WATER MONITORING		<u>[XX]</u>	\Box	П	ĹĬ
e.	EFFLUENT LIMITATIONS		XX	Π		ΞĬ
5.	EXPLOSIVES		[XX]	П	Ш	\Box
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES		XXI	ΙĪ	\square	\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		П	[XX]	Ц	. []
8.	NONCOAL WASTE		[XX]	Ш	[XX]	Ш
9.	PROTECTION OF FISH, WILDLIFE AND					
	RELATED ENVIRONMENTAL VALUES		[XX]	\Box	\Box	\Box
0.	SLIDES AND OTHER DAMAGE		[XX]	\Box		Ш
1.	CONTEMPORANEOUS RECLAMATION		[XX]	Ш		\Box
2.	BACKFILLING AND GRADING		[XX]		\Box	\Box
3.	REVEGETATION		[XX]	Ш	\Box	П
4.	SUBSIDENCE CONTROL		[XX]	Ш	\Box	\Box
5.	CESSATION OF OPERATIONS		[XX]	\Box	\Box	\Box
6.	ROADS:					
a.	CONSTRUCTION/MAINTENANCE/SURFACING		[XX]	Ц	\Box	\Box
b.	DRAINAGE CONTROLS		[XX]		\Box	\Box
7.	OTHER TRANSPORTATION FACILITIES		[XX]	Ц	\Box	\Box
8.	SUPPORT FACILITIES/UTILITY INSTALLATIONS		[XX]	П	\Box	\Box
9.	AVS CHECK (4th Quarter-April, May, June)(date)		[XX]	\Box		. []
20.	AIR QUALITY PERMIT		[XX]	\Box	\Box	\Box
1.	BONDING & INSURANCE		[XX]	\Box		\Box



INSPECTION REPORT

(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: 11/12/96

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -

- a) The permittee performed monthly inspections for third quarter on the sediment pond. There were no hazardous conditions reported.
- b) The third quarter NPDES self-monitoring reports were reviewed with no discharge of water occurring.
- c) The legal and financial information of Genwal was updated on April 18, 1996.
- d) The SPCC Plan was updated by a certified P.E. on October 18, 1996.
- e) Reviewed the reclamation agreement, which was signed in March of 1995. The amount was \$703,000. The Division and the Permittee have signed the document.

4A. DIVERSIONS -

The diversion catch basin next to the loadout has started to fill-up with sediment. The operator has committed in cleaning the sediment trap. Other diversions were spotchecked and were in compliance.

4B. SEDIMENT POND -

The sediment pond was cleaned in October and the permittee will be submitting updated as-builts. The inspection revealed no signs of erosion or hazardous conditions.

4C. OTHER SEDIMENT CONTROL MEASURES -

Silt fences and straw bales are used for the alternate sediment control measures at Genwal. Several of the ASCA areas were inspected and complied with the designs in the Mining and Reclamation Plan.

INSPECTION REPORT

(Continuation sheet)

Page <u>3</u> of <u>3</u>

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: 11/12/96

(Comments are Numbered to Correspond with Topics Listed Above)

8. NONCOAL WASTE -

There was one used fuel filter near the sediment pond, which most likely came from the coal trucks. The mine property was cleared of non-coal waste except for this filter. The filter was picked up and put into a trash container.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Genwal Resources, Inc.

Marcia Petta (OSM)

Given to: <u>Joe Helfrich (DOGM)</u> Filed to: <u>Price Field Office</u>

Date: November 21, 1996

Inspector's Signature:_

phen J. Demczak

#20